13 December 1965

STATINTL

Subject: ECP GR-28A, Contract LP 2264

Dear Chuck,

STATINTL

This ECP is technically approved by the SPO. The proposed method of handling this change is preferable to the original ECP's. Request you provide formal approval of this change to

Also, advise Nat that his revised handbook and aperture cards should point out that the 531A401-030-130 TR tube is the proper replacement part for TR tubes in the first sixteen receivers.

	regards,
STATINTL	
Copy:	

•	GA	- 531			INEERING ST			GR-	28 Rev A	A		
DATE	11-23-6	5	·	AFFECTS	s: REC	EIVER						
NAME O	F MAJOR CO	MPONENT	PA	RT OR LOV	VEST SUBASS	MBLY		PART NO				
Re	Receiver			TR-Tube	TR-Tube assembly				MODEL OR TYPE 531A401-030-103 (New P/N 531A401-030-101 (Old P/N			
TITLE OF	PROPOSAL:	TR-	TUBE SEA	LS						20 m		
NATURE	OF PROPOSA	L:	· · · · · · · · · · · · · · · · · · ·						. 13			
. A	pply pott	ing (RTV) around	tube s	eal with	contact	to tu	be body	7.•			
REASON	FOR PROPOS	SAL:										
				tubes	resultin	g from d	amage	to seal	ls during			
ma	intenance	and har	ndling.	•		× .						
										Ž.		
	•											
			s	1								
120:												
ES	ESTIMATED	STIMATED COST AND TIME INVOLVED:										
	ADDITIONA	AL FUNDING	REQUIRED:	UIRED: N/A								
CP			CITS OR PART		N/A					. 建聚合		
	<u> </u>		REQUIRED:									
ITEMS A	FFECTED BY P	'ROPOSAL:		003-17 a	and subs	in line.	•					
SAFETY	MISSION EFFEC- TIVENESS	PERFORM- ANCE	OPERATING PROCEDURE	INTER- CHANGE- ABILITY	WEIGHT OR WEIGHT AND BALANCE	TOOLS AND SUPPORT EQUIPMENT	NANCE PROCEDU	RE LIFE	MANUAL	mentions.		
ᅵ		Z.										
ESTIMAT	ED MAN HOL	JRS REQUIRE	D TO ACCO	MPLISH CI	HANGE IN F	IELD:						
SOURCE	OF PARTS FO	OR KIT:	₹ .		,	AVAILABILIT	Υ	4 WE	EKS AFTER AP	PROVAL		
DISPOSI	ITION OF SPA	RES AFFECT	ED: Spar	res to 1	oe rework	ed to la	test c	onfigu	ration.			
ST	ATINTL		PPB	will be	e changed	by char	ng e n ot	ice to	PSO.			
INI										1.5		